#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/Ala Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020883 Address: 333 Burma Road **Date Inspected:** 15-Feb-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes No N/A **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** Components

### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.


#### Bay 14

During a random observation, this QA Inspector observed the following components for the Orthotropic Bridge Girder (OBG) in Bay 14: Segments 14E and 14W. This QA Inspector observed that ZPMC was not performing any welding on the above mentioned components during the time this QA Inspector was present. However, an arc strike was observed on a Segment 14E deck panel, transverse diaphragm near the U-rib to transverse diaphragm weld joint DP3167-001-260. This QA Inspector clearly marked the visual indication in yellow paint with the notation G+MT, signifying 'grind smooth and magnetic particle test' and informed ZPMC QC Guo Xin Hui (QCA1) of the arc strike and marking. See the photo below. QCA1 informed this QA Inspector that the arc strike would be corrected in a manner compliant with the relevent contract documents.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)



# **Summary of Conversations:**

As noted above.

# **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Goulet,George	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer